

Technical Service Bulletin

SUBJECT:
Fuel Filler Cap Is
Difficult To Remove

NO: 14-07-98
GROUP: Fuel

DATE: Dec. 11, 1998

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, without written permission of DaimlerChrysler Corporation.

THIS REPAIR IS COMPATIBLE WITH DAIMLERCHRYSLER'S MOBILE SERVICE PROGRAM AND DOES NOT REQUIRE HOISTS OR OTHER FULL SERVICE FACILITY SPECIAL EQUIPMENT.

MODELS:

1999 (WJ) Grand Cherokee

NOTE: THIS BULLETIN APPLIES TO VEHICLES BUILT BEFORE SEPTEMBER 21, 1998 (MDH 0921XX). VEHICLES BUILT AFTER THAT DATE ARE EQUIPPED WITH THE REVISED FUEL FILLER CAP.

SYMPTOM/CONDITION:

The seal on the fuel filler cap may stick in the filler neck, making the cap difficult to remove. A new cap with a revised seal has been released to address this condition.

DIAGNOSIS:

If customers complain of having difficulty removing the fuel filler cap on vehicles built before September 21, 1998 (MDH 0921XX), perform the Repair Procedure.

PARTS REQUIRED:

1 52100420AA Cap

REPAIR PROCEDURE:

This bulletin involves Replacing the fuel filler cap.

1. Remove the fuel filler cap.
2. Install filler cap, p/n 52100420AA.

14-07-98

-2-

POLICY: Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No: 14-65-05-90 0.2 Hrs.

FAILURE CODE: P8 - New Part