

Technical Service Bulletin

NUMBER: 19-06-00

GROUP: Steering

DATE: Sept. 15, 2000

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, without written permission of DaimlerChrysler Corporation.

SUBJECT:

Steering Gear Honk On Turns

OVERVIEW:

This bulletin involves installing a revised steering gear.

MODELS:

1999 - 2000 (WJ) Grand Cherokee (Including US and European built vehicles)

SYMPTOM/CONDITION:

A honking sound may be heard when making slow speed sharp turn such as turning into a driveway. The sound will normally happen when making right turns with left hand drive vehicle and when making left turns with right hand drive vehicles.

DIAGNOSIS:

If the noise is present, perform the Repair Procedure.

PARTS REQUIRED:

52088272AD	Steering Gear - US Built Vehicles
52088273AC	Steering Gear - European Built Left Hand Drive Vehicles
52088471AC	Steering Gear - European Built Right Hand Drive Vehicles

REPAIR PROCEDURE:

1. Using the procedures outlined in the appropriate Grand Cherokee Service Manual, remove the steering gear and replace it with the part listed above.

POLICY: Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:

Steering Gear Assy. - Replace - Left Hand Drive	
19-00-01-95	1.1 Hrs.
Steering Gear Assy. - Replace - Right Hand Drive	
19-00-01-96	1.4 Hrs.
Skid Plate Equipped	
19-00-01-60	0.2 Hrs.

FAILURE CODE: P8 - New Part