

Technical Service Bulletin

NUMBER: 14-01-99

GROUP: Fuel

DATE: Feb. 19, 1999

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, without written permission of DaimlerChrysler Corporation.

SUBJECT:

Slow Fuel Fill

OVERVIEW:

This Bulletin Involves installing a revised fuel filler tube.

MODELS:

1999 (WJ) Grand Cherokee

SYMPTOM/CONDITION:

Customers may experience slow fuel fill or repeated fuel pump nozzle shut off.

DIAGNOSIS:

If customers complain of this condition, perform the Repair Procedure.

PARTS REQUIRED:

1 05016128AA Fuel Filler Tube

REPAIR PROCEDURE:

1. Raise the vehicle on a hoist.
2. Loosen the hose clamps on the vent and fuel fill hoses at the fill tube end.
3. Remove the vent and fill hoses from the filler tube assembly.
4. Remove the fuel filler cap.
5. Remove the three filler tube attaching screws and remove the filler tube assembly.
6. Install the new filler tube, p/n 05016128AA with the three attaching screws. Snug the three screws and then final tighten them to 1.8 Nm (15 in. lbs.) in the following sequence: First - upper right, Second - lower left, Third - lower right.
7. Install the vent and fill hoses to the filler tube assembly and tighten the clamps to 3 Nm (25 in. lbs.).
8. Install the fuel filler cap.

POLICY: Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No: 14-60-15-93 0.3 Hrs.

FAILURE CODE: P8 - New Part