



**NUMBER:** 23-08-00 REV. B

**GROUP:** Body

**DATE:** Nov. 24, 2000

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of DaimlerChrysler Corporation.*

**THIS BULLETIN SUPERSEDES TECHNICAL SERVICE BULLETIN 23-08-00 REV. A, DATED JULY 7, 2000, WHICH SHOULD BE REMOVED FROM YOUR FILES. ALL REVISIONS ARE HIGHLIGHTED WITH \*\*ASTERISKS\*\* AND INCLUDE ADDITIONAL MODELS AND PARTS.**

**SUBJECT:**

Child Seat Tether Anchors

**MODELS:**

1989 - 1995	(AA)	Spirit/Acclaim/LeBaron Sedan
1989 - 2000	(AB)	Ram Van/Wagon
1989 - 1993	(AC)	Dynasty/New Yorker/New Yorker Salon
1989 - 1994	(AG)	Daytona
1989	(AH)	Lancer/Lebaron GTS
1989 - 1993	(AJ)	Lebaron Coupe
1989 - 1990	(AK)	Aries/Reliant
1989 - 1990	(AL)	Horizon/Omni
1989	(AM)	Diplomat/Gran Fury/New Yorker Fifth Avenue
1989 - 2000	(AN)	Dakota
1989 - 1994	(AP)	Shawdow/Sundance
1989 - 1995	(AS)	Town & Country/Caravan/Voyager
1990 - 1993	(AY)	Imperial/New Yorker Fifth Avenue
1988 - 1992	(BB)	Monaco/Premier
1990 - 1994	(BD)	Laser/Talon
1994 - 2001	(BR/BE)	Ram Truck
1989 - 1992	(B2)	Colt/Summit
1992 - 1995	(B3)	Colt Vista
1989	(B5)	Conquest
1989 - 1995	(B7)	Stealth (2000 GTX Dodge/Eagle, Canada)
1992 - 1995	(B8)	Colt Vista Wagon/Summit Wagon
1993 - 1994	(B9)	Colt/Summit



**Stick with the Specialists™**

1998 - 2000	(DN)	Durango
1995 - 1999	(FJ)	Sebring/Avenger/Talon
1995 - 1999	JA	Cirrus/Stratus/Breeze
1993 - 1999	(LH)	Concorde/Intrepid/Vision/LHS/New Yorker/300M
1996 - 2000	(NS)	Town & Country/Caravan/Voyager
1995 - 2000	(PL)	Neon
1997 - 1999	(PR)	Prowler
1996 - 1999	(SR)	Viper/Viper GTS
**2000	(TJ)	Wrangler**
1999 - 2000	(WJ)	Grand Cherokee
1989 - **2000**	(XJ)	Cherokee/Wagoneer
1993 - 1998	(WJ)	Grand Cherokee/Grand Wagoneer

**NOTE: THIS BULLETIN IS PROVIDED TO IDENTIFY THE PARTS AND LABOR OPERATION NUMBERS NECESSARY TO INSTALL A CHILD SEAT TETHER ANCHOR. DAIMLERCHRYSLER WILL REIMBURSE YOU FOR THE ANCHORS AND LABOR TO INSTALL THEM. THIS IS BEING DONE IN THE INTEREST OF CUSTOMER SATISFACTION. REFER TO GLOBAL WARRANTY ADMINISTRATION BULLETIN #D-99-23 FOR COMPLETE REIMBURSEMENT INSTRUCTIONS.**

***DISCUSSION:***

User-ready child restraint tether strap anchors will be provided in passenger cars in the 2000 Model Year, and in light trucks in the 2001 Model Year. Tether straps improve the performance of child restraints in collisions. Because of the publicity that has accompanied the "Fit for a Kid" Program, owners of earlier products are expected to approach dealers for the free provision and installation of the anchor hardware. DaimlerChrysler Corporation is offering child seat tether anchors for the selected vehicles listed above. Each tether anchor is packaged in a kit containing all necessary parts and a detailed instruction sheet.

***PARTS REQUIRED:***

BODY	MODEL	YEAR	CENTER	OUTBOARD
AA	Lebaron Sedan/Spirit/Acclaim	89-95	04519071AB	04519071AB
AB	Ram Wagon	89-00	04358469AB	04358469AB
AC	New Yorker/Landau/Dynasty	89-93	04519073AB	04519072AB
AG	Daytona	89-90	NA	05003422AB
AG	Daytona	91-94	NA	04519074AB
AH	Lancer/Lebaron GTS	89	04519076AB	05003422AB
AJ	LeBaron Coupe	89-93	04519077AB	04519077AB
AK	Aries/Reliant	89-90	04519077AB	04519077AB
AL	Horizon/Omni	89-90	04519081AB	04519080AB

AM	Diplomat/Gran Fury/New Yorker Fifth Avenue	89	04519077AB	04519077AB
AN	Dakota	88-99	05014765AA	05014765AA
AN	Dakota, AN84	00	05016573AA	05016573AA
AN	Dakota, Extended Cab	00	05016572AA	05016572AA
AN	Dakota, Standard Cab	00	05017683AC	05017683AC
AP	Shadow/Sundance	89-94	04519292AB	04519292AB
AS	Town & Country/Caravan/Voyager	89-95	05017529AB	05017529AB
AY	Imperial/New Yorker Fifth Avenue	90-93	04519071AB	04519071AB
BB	Monaco/Premier	89-92	04519077AB	04519077AB
BD	Laser/Talon	90-94		
	Anchor		MB590094	MB590094
	Bolt		MF140227	MF140227
	Bracket Left		MB593349	MB593349
	Bracket Right		MB593350	MB593350
BR/BE	Ram Truck, Built Prior To Sept. 20, 2000	94-01	05017032AB	05017032AB
B2	Colt/Summit	89-92		
	4-Door		MB597261	MB612814
	2-Door		MB865730	MB597261
B3	Vista	92-95	MB583400	MB583400
5	Chrysler Conquest	87-89	MB597261	MB597261
B7	2000GTX Dodge/Eagle-Canada	89-91	MB597261	MB597261
	Stealth	92-95	MB597261	MB597261
B8	Colt Vista/Summit Wagon	92-95	MB583400	MB583400
B9	Colt/Summit	93-94		
	4-Door		MB865730	MB865730
	2-Door		MB597261	MB597261
DN	Durango	98-00		
	Standard Seat (60/40)		NA	05015403AA
	40/20/40 Seat			05012007AB
FJ	Avenger/Sebring	95-99	MB597261	MB612814
FJ	Talon	95-97	MB583400	MB583400
JA	Breeze.Cirrus/Stratus	95-99	04519077AB	04519077AB
LH	Intrepid/Concorde/Vision	93-99	04519077AB	04519077AB
	New Yorker/LHS	94-97	04519077	05017645AA

	LHS/300M	99	04519077AB	04519077AB
NS	Town & Country/Caravan/Voyager	96-00		
	2nd Row Seats		04864118AB	04864118AB
	3rd Row Seats		05018506AA	05018506AA
PL	Neon, Built Prior To July 26, 1999	95-00	05017563AB	05017563AB
PR	Prowler	97-99	NA	05017570AA
SR	Viper	96-99	NA	04883004AB
**TJ	Wrangler	00	NA	05066347AA**
WJ	Jeep Grand Cherokee - Canada	99-00	NA	05016871AA, Camel Trim
				05016873AA, Taupe Trim
WJ	Jeep Grand Cherokee - US	99-00	NA	05016869AA, Camel Trim
				05016870AA, Taupe Trim
XJ	Jeep Cherokee	89-99	NA	05003422AB
		**00	NA	05066385AA**
ZJ	Jeep Grand Cherokee/Grand Wagoneer	93-98	04728952AB	NA

**POLICY:**

Customer Satisfaction

**TIME ALLOWANCE:**

Labor Operation No:	Description	Vehicle/Year	Allowance
23-13-12-90	Anchor, Child Seat Tether - Install One	1989-1995 (AA)	0.2 Hrs.
		1989-1994 (AG,AP)	0.2 Hrs.
		1989 (AH,AM)	0.2 Hrs.
		1989-1993 (AJ)	0.2 Hrs.
		1989-1990 (AK, AL)	0.2 Hrs.
		1988-1992 ((BB)	0.2 Hrs.
		1994-2001 (BR/BE)	0.2 Hrs.
		1998-2000 (DN)	0.2 Hrs.
		1995-1999 (JA)	0.2 Hrs.
		1995-2000 (PL)	0.2 Hrs.
		1996-1999 (SR)	0.2 Hrs.

		**2000 (TJ)	0.2 Hrs.**
		1989-1993 (AC)	0.3 Hrs.
		1990-1993 (AY)	0.3 Hrs.
		1995-1999 (FJ)	0.3 Hrs.
		1993-1999 (LH)	0.3 Hrs.
		**2000 (XJ)	0.3 Hrs.**
		1989-1995 (AS)	0.4 Hrs.
		1996-2000 (NS)	0.4 Hrs.
		1989-1999 (XJ)	0.4 Hrs.
		1993-1998 (ZJ)	0.4 Hrs.
		1989-2000 (AB)	0.5 Hrs.
		1989-1995 (B7)	A/T
		1990-1994 (BD)	A/T
		1989-1992 (B2)	A/T
		1992-1995 (B3,B8)	A/T
		1989 (B5)	A/T
		1993-1994 (B9)	A/T
		1999-2000 (PR)	A/T
23-13-12-91	Anchor, Child Seat Tether - Install Two	1994-2001 (BR/BE)	0.2 Hrs.
		1989-2000 (DN)	0.2 Hrs.
		1989-1995 (AA)	0.3 Hrs.
		1989-1994 (AG)	0.3 Hrs.
		1989 (AH, AM)	0.3 Hrs.
		1989-1993 (AJ)	0.3 Hrs.
		1989-1990 (AK, AL)	0.3 Hrs.
		1989-1994 (AP)	0.3 Hrs.
		1988-1992 (BB)	0.3 Hrs.
		1995-1999 (JA)	0.3 Hrs.
		1995-2000 (PL)	0.3 Hrs.
		1999-2000 (WJ)	0.3 Hrs.
		1989-1993 (AC)	0.4 Hrs.
		1990-1993 (AY)	0.4 Hrs.
		1993-1999 (LH)	0.4 Hrs.
		1989-1995 (AS)	0.5 Hrs.

		1996-2000 (NS)	0.5 Hrs.
		1989-1999 (XJ)	0.6 Hrs.
		1989-2000 (AB)	0.7 Hrs.
		1989-2000 (AN)	1.0 Hrs.
23-13-12-92	Anchor, Child Seat Tether - Install Three	1994-2001 (BR/BE)	0.2 Hrs.
		1989-1995 (AA)	0.4 Hrs.
		1989 (AH, AM)	0.4 Hrs.
		1989-1993 (AJ)	0.4 Hrs.
		1989-1990 (AK, AL)	0.4 Hrs.
		1989-1994 (AP)	0.4 Hrs.
		1988-1992 (BB)	0.4 Hrs.
		1995-1999 (JA)	0.4 Hrs.
		1995 2000 (PL)	0.4 Hrs.
		1989-1993 (AC)	0.5 Hrs.
		1990-1993 (AY)	0.5 Hrs.
		1993-1999 (LH)	0.5 Hrs.
		1996-2000 (NS)	0.6 Hrs.
		1989-2000 (AN)	1.2 Hrs.
23-13-12-93	Anchor, Child Seat Tether - Install One - Third Seat	1996-2000 (NS)	0.3 Hrs.
23-13-12-94	Anchor, Child Seat Tether - Install Two Or Three - Third Seat	1996-200 (NS)	0.4 Hrs.

**FAILURE CODE:**

CG	Customer Satisfaction
----	-----------------------